

BitRaser Diagnostics Report

Report Information

Report ID: 179

Digital Identifier: 3d8d96f5bdfd235c2df35fa88b0845aa

Report Date: July 31, 2025 02:22:31 CST

Software Version: BitRaser Hardware Diagnostics 3.0.0.9

Customer Details

Customer Name: John Doe

Customer Address: Las Vegas Nevada

Summary

Total Test: 16

Test Performed: 16

Start Time: July 31, 2025 02:01:36 CST

Duration: 00:09:28

Test Passed: 16

Test Failed: 0

End Time: July 31, 2025 02:11:04 CST

Status: Completed

Test	Test Type	Part Exists	Tested	Result	Error Found
CPU:	Auto	Yes	Yes	Pass	0
Memory:	Auto	Yes	Yes	Pass	0
Battery:	Auto	Yes	Yes	Pass	0
Storage:	Auto	Yes	Yes	Pass	0
GPU:	Auto	Yes	Yes	Pass	0
Monitor:	Auto	Yes	Yes	Pass	0
CMOS:	Auto	Yes	Yes	Pass	0
System Board:	Auto	Yes	Yes	Pass	0
Keyboard:	Manual	Yes	Yes	Pass	0
Mouse/TouchPad:	Manual	Yes	Yes	Pass	0
Audio:	Manual	Yes	Yes	Pass	0
Display:	Manual	Yes	Yes	Pass	0
Wifi:	Manual	Yes	Yes	Pass	0
Bluetooth:	Manual	Yes	Yes	Pass	0
USB Port:	Manual	Yes	Yes	Pass	0
Accessories And Grading:	Manual	Yes	Yes	Pass	0

Machine Information

Manufacturer: Apple Inc.

Model: Mac15.12

System Serial: HJMTXMFHN6

Chassis Serial: HJMTXMFHN6

Board Serial: HJMTXMFHN6

Media Source: Graphic Designing

Chassis Type: Laptop (EMC: 8611)

UUID: 9C18A233-972B-5857-9425-667922AAD153

USB Hub: 4

Memory (RAM): 8 GB

Asset Tag: TAGEXAMPLE12345

Media Destination: HR

Diagnostics & Validation Details

Technician Name: John Schmo

Validator Name: Jane Doe

Organization: Dummy Corporation 1

Organization: Dummy Corporation 2

I hereby state that the Diagnose process has been carried out in accordance with the given specifications

Date: July 31, 2025 02:22:31 CST

Sample Signature

Sample Signature

Diagnostics Technician

Validator